



(Version January 2021)

| Certification Body: | SZÚ | | | |
|---|-------------------|---------------|-------------------------------|--|
| Inspection Body: | SZÚ | Inspector: | Ing. Petr Smolinský | |
| Date of inspection: | 27.10.2022 | | | |
| Contact Data | | | | |
| Company: HRA | NEX s.r.o | Nová Pláň č.p | o. 26, 792 01, Czech Republic | |
| Site: HRANEX s.r.o Address: Bílčice 107, 793 68 Dvorce, Czech Republic | | | | |
| ENplus® ID: CZ 020 | | | | |
| Quality Manager: | Oldřiška Snopková | Email QM: | aborator@hranex.cz | |
| Business activities (except activities of se | | | | |
| Production | | X yes | | |
| Full load deliveries of bulk pellets to end-users 1) | | | | |
| Part load deliveries of bulk pellets to end-users ²⁾ yes no new business ⁴⁾ | | | | |
| Bagging of pellets 3) | | yes no | new business 4) | |
| Sourcing pellets from another certified company 2) yes no new business 4) | | | | |
| ¹⁾ including unsealed Big Bags ²⁾ separate trader conformity report needed ³⁾ including sealed Big Bags ⁴⁾ since previous conformity assessment | | | | |





(Version January 2021)

| Product (all information | valid for the previous calendar year) | | | |
|---|---|--|---------------------------|--|
| Quality classes: | ■ ENplus A1® | plus A2® ENplus B® | Other | |
| Total amount of produced pellets (in metric tons): | | EN <i>plus</i> A2®: Other: | $\frac{0}{0}$ t | |
| Amount of pellets (ENplus A1®, ENplus A2® & ENplus B® quality) sold to power plants or for animal bedding, included in the numbers above (in metric tons) | | | | |
| Carbon footprint | bagged pellets 34,12 | g CO2-eq./ kg pellets g CO2-eq./ kg pellets | | |
| Brand names (ba | agged pellets): HRANEX | Pellets | | |
| management | proved by the international ve not been approved by the compe | yes etent management, please ad | no d pictures of the bags | |
| Comment(s): The bag design approved on 24.09.2020. | | | | |
| Raw materia | I | | | |
| Sources: | 0 % virgin wood (1.1) 100 | % residues (1.2) <u>0</u> | % used wood (1.3) | |
| Sustainability: | 0 % of (1.1) from certified sou 82 % of (1.2) from certified Cha | | N/A PEFC | |
| Species: | 100 % spruce 0 % pine | 0 % hardwood | 0 % other | |
| Additives: Comment(s): | None W-% of pellets Type of a | additives: None | | |





(Version January 2021)

(please list names of uncertified service provider respective Service Provider Registration Numbers of certified service provider and add the code for activities in brackets)

| certifica service | provider | and dad the code it | or activities in brac | one to j | | |
|------------------------------|-------------|----------------------------------|-----------------------|--------------|----------------|----------------|
| Activity codes: | | | | | | |
| (a) Bagging | | | | | | |
| (b) Full load deliv | ery to e | nd-users | | | | |
| (c) Part load deliv | veries to | end-users (only trac | ders) | | | |
| (d) Storage | | | | | | |
| (e) Loading/Unlo | _ | | | | | |
| (f) Transport to t | | , | | | | |
| (g) Others (pleas | | - | | | | |
| Certified SPs | N | /A | | | | |
| Non-certified SPs | N | /A | | | | |
| Comment | N | one | | | | |
| Storage sites | | | | | | |
| _ | operated | d by non-certified se | rvice providers) | | | |
| | • | , | 1 hall | | | |
| Total number of | (relevan | t ⁵⁾) storage sites: | | | | |
| Addresses of insp | ected st | torage sites: | Bílčice 107, 79 | 93 68 Dv | orce, Czech | Republic |
| 5) Stores with faci | ilities for | loading trucks for e | nd-user delivery, i | incl. equipi | ment for separ | ation of fines |
| Complaints (from traders and | d end-us | ers) | | | | |
| Total: 0 | _ | accept | ed: 0 | _ | rejected: | 0 |
| Reasons for com | plaints: | | | | | |
| fines: | 0 | % of complaints | | | | |
| durability: | 0 | % of complaints | | | | |
| overlength: | 0 | % of complaints | | | | |
| smell: | 0 | % of complaints | | | | |
| contamination: | 0 | % of complaints | Please specify: | N/A | | |
| other: | 0 | % of complaints | Please specify: | N/A | | |





(Version January 2021)

| Inspection results (including non-certified service provi | iders) | | |
|--|--|--------------------|--|
| Major changes since the previous inspection (e.g. additional stores, new quality manager) | New pag | ckaging line. | |
| Type C non-conformities: | yes | no no | solved |
| Description of type C non- conformities and measures taken: | | | |
| Comments / observations | | | |
| The company did not work from the part of the company deliver. The above-named pellet pro | ing raw ma | aterial for th pel | llet plant. |
| providers if relevant) confor programme as specified in the | ms to the | requirements | s of the EN <i>plus®</i> certification |
| y | es . | no | |
| Brno, 2022-11-1 (place and date) | A SAR ASSERTING THE PROPERTY OF THE PROPERTY O | T - / | nature and company stamp) |
| Attachments | | 2 | |
| GHG calculation (completed Exce | | | |
| GNG calculation (completed Excel | l sheet) | | |
| Picture(s) of non-approved bag de | · | | |

- Send to the competent management (enplus@bioenergyeurope.org) -